

REV	ECO	DATE	DESCRIPTION	D.B.
E	5455	6/13/16	Add notes Build 7.0.0.8915 and Intermediate builds	JS

WinMark Pro v7 Release Notes

Version 7.0.0.8141

ECO 4978 4/29/2014

- Release to Production

Version 7.0.0.8309

ECO 5068 10/2/2015

- Improved boundary checking for sloped and stepped surfaces
- Fix heartbeat timeout errors
- Digiscope and Launcher crash when diode pointer is active.
- Increase upper limit of PWM frequency to 200 kHz for f201.
- Diode pointer not working correctly in SA mode.
- Abort button in Mark window not working properly.
- Abort from 2d Barcodes or entities with multiple passes not working properly.

Version 7.0.0.8601

ECO 5255 7/21/2015

- Field Correction algorithm for < 0.1 mm precision
- Support of alternate wavelengths (9.3, 10.2)
- Fine Z-Axis adjustment feature
- Sensor distance offset for consistency between heads in Tracking.
- Bug Fix: Abort from control file not working.
- Bug Fix: Vector import scale property does not persist between WinMark Sessions.
- Bug Fix: Changing field sizes can fault out head and blow fuse.

Version 7.0.0.8858

ECO 5419 04/12/2016

- Remove USB Hardlock functionality from WinMark Pro V7 software.

Version 7.0.0.8915

ECO 5455 06/13/2016

- BUG FIX: WinMark does not mark barcodes & 2D bar codes.
- BUG FIX: Mark automation is disabled.
- BUG FIX: Object properties that are changed revert to default values when WinMark is restarted.
- NEW FEATURE: Activx method allows user to set object marking order.

<small>Proprietary. This document is proprietary to Synrad Inc. and shall not be used or disclosed in whole or in part without written permission from Synrad, 4600 Campus Place, Mukilteo, WA 98275.</small>			
Synrad		Description: Release Notes, WinMark Pro v7	
Part #: 112-20830-01		File #: 311-20830-01E	Page 1 of 1
Drawn by: Stevan Saban	Checked by: <i>Eyenne Miller</i>	Date: 6/14/16	
Date: 7/21/2015	Approved by: <i>Jeff Englund</i>	Date: 6/15/16	